

<b>Din 5480</b>									
<b>X = Jahns</b>		Maße	Vorbohr.	R. L.	Züge	Bohr	Kugel	Soll Maß	Ist Maß
N20x1,25x30x14x9H	m1,25 z14 30°	17,2 H8	20-50	1	Ja				
N25x1,25x30x18x9H	m1,25 z18 30°	22,3 H8	20-60	1	Ja				
N32x1,25x30x24x9H	m1,25 z24 30°	29,5 H7	35	1	Nein				
N35x1,25x30x26x9H	m1,25 z26 30°	32,5 H7	30-110	1	Nein				
N30x2x30x14x9H	m2 z14 30°	25,85 H8	25-80	1	Ja	3,5	29,55-29,65	29,64-29,66	
N32x2x30x14x8H	m2 z14 30°	27,8 H8	28-84	1	Ja				
N35x2x30x16x7H	m2 z16 30°	30,8 H8	16-40	1	Ja	3,5	34,74-34,78	34,76	
N40x2x30x18x9H	m2 z18 30°	36,0 H7	26-52	1	Nein	3,5	39,78-39,85	39,84	
N40x2x30x18x9H	m2 z18 30°	36,0 H7	42-84	1	Nein	3,5	39,78-39,85	39,84	
N45x2x30x21x9H	m2 z21 30°	40,7 H8	20-50	1	Ja				
N50x2x30x24x8H	m2 z24 30°	45,8 H8	28-84	1	Ja	3,5	49,66-49,72	42,72	
N50x2,5x30x18x9H	m2,5 z18 30°	45 H7	105	1	Nein				
N70x3x30x22x9H	m3 z22 30°	64,0 H7	0-45	2	Nein				
N75x3x30x24x9H	m3 z24 30°	68,8 H8	19-100	2	Ja				
N75x3x30x24x9H	m3 z24 30°	68,8 H8	22-55	1	Ja				
N80x2,5x30x30x9H	m2,5 z30 30°	75,0 H7	120	2	Nein				
N95x3x30x30x9H	m3 z30 30°	88,7 H8		1					
N60x1,25x30x46x7H	m1,25 Z46 30°	57,5 H7	25 -63	1	Nein				HAWE
<b>DIN 5481</b>	Maße	Vorbohr.	R. L.	Züge					
	12 x 14 Z 31	12,3 H8	12-35	1					
	15 x 17 Z 32	15,2 H8	14-40	1					
	17 x 20 Z33	17,6 H8	14-40	1					
	21 x 24 Z34	21,1 H8	16-25	1					
	26 x 30 Z35	26,8 H8	24-84	1					
	40 x 44 Z38	40,31 H8	24-60	1					
<b>DIN 5482</b>	Maße	Vorbohr.	R. L.	Züge					

ZN 58 x 53	m2 z27 30°	52,8 H8	25-70	1				